



Характеристики

Рабочее давление	2 - 25 bar
Измерение расхода воздуха	At P1 = 6 bar and pressure drop Δp = 1 bar



Информация о продукте

Резьба	G 1/2
Расход пот.	3800 l/min
A	70 mm

A	70 mm
Рабочее давление, бар	2 - 25 bar
B	72,0 mm

Указания

Прочие данные только по запросу.

Описание

For slow pressure build-up in pneumatic systems, e.g. after an emergency stop. The valve opens to full flow at approximately 60% of the set operating pressure.

The filling time can be set by turning the adjusting screw. Used in combination with multi-piece service units.